



# Asbestos Assessment

Sacred Heart of Jesus  
5 Hamilton Ave, Hamilton, ON, L8V  
2SC

Prepared for:

**Hamilton-Wentworth Catholic  
District School Board**

90 Mulberry Street  
Hamilton, Ontario, L8N 3R9

August 31, 2023

Pinchin File: 320582.004



**Asbestos Assessment**

Sacred Heart of Jesus, 5 Hamilton Ave, Hamilton, ON, L8V 2SC  
Hamilton-Wentworth Catholic District School Board

August 31, 2023  
Pinchin File: 320582.004

**Issued to:** Hamilton-Wentworth Catholic District School Board  
**Issued on:** August 31, 2023  
**Pinchin File:** 320582.004  
**Issuing Office:** Hamilton, ON  
**Primary Contact:** Emily Balfour, Project Manager, [ebalfour@pinchin.com](mailto:ebalfour@pinchin.com)

---

Author: \_\_\_\_\_  
Emily Balfour  
Project Manager  
365.889.5147  
[ebalfour@pinchin.com](mailto:ebalfour@pinchin.com)

Reviewer: \_\_\_\_\_  
Damian Palus, C.E.T.  
Operations Manager  
289.678.0694  
[dpalus@pinchin.com](mailto:dpalus@pinchin.com)



## **EXECUTIVE SUMMARY**

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials assessment of Sacred Heart of Jesus located at 5 Hamilton Ave, Hamilton, ON, L8V 2SC.

The objectives of the assessment were to document the locations of asbestos building materials, evaluate their condition and develop corrective action plans as required for the purposes of long-term management. The results of this assessment are not intended for construction, renovation, demolition or project tendering purposes.

## **SUMMARY OF RECOMMENDATIONS**

The following is a summary of significant recommendations; refer to the body of the report for detailed recommendations:

1. Maintain the Asbestos Management Program (AMP)
2. Perform a re-assessment of asbestos materials on an annual basis.
3. Perform a pre-construction assessment and remove all ACM prior to alteration or maintenance work if ACM may be disturbed by the work.
4. Follow appropriate safe work procedures when handling or disturbing asbestos.
5. Sample any presumed ACM prior to alteration or maintenance work if presumed ACM may be disturbed by the work.
6. Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

*This Executive Summary is subject to the same standard limitations as contained in the report and must be read in conjunction with the entire report.*



**TABLE OF CONTENTS**

1.0 INTRODUCTION AND SCOPE ..... 1  
    1.1 Scope of Assessment ..... 1  
2.0 METHODOLOGY ..... 1  
3.0 BACKGROUND INFORMATION ..... 1  
    3.1 Building Year of Construction and Additions ..... 1  
    3.2 Existing Reports ..... 1  
    3.3 Inaccessible Locations ..... 2  
4.0 FINDINGS ..... 2  
    4.1 Excluded Asbestos Materials ..... 2  
    4.2 Summary of Building Materials ..... 3  
5.0 RECOMMENDATIONS ..... 5  
    5.1 General ..... 5  
    5.2 Remedial Work ..... 5  
    5.3 On-going Management and Maintenance ..... 5  
6.0 TERMS AND LIMITATIONS ..... 6  
7.0 REFERENCES ..... 6

**APPENDICES**

APPENDIX I Drawings  
APPENDIX II Asbestos Analytical Certificates  
APPENDIX III Methodology  
APPENDIX IV Location List  
APPENDIX V Summary Report / Sample Log  
APPENDIX VI HMIS All Data Report



## 1.0 INTRODUCTION AND SCOPE

Hamilton-Wentworth Catholic District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos building materials assessment of Sacred Heart of Jesus located at 5 Hamilton Ave, Hamilton, ON, L8V 2SC.

Pinchin performed the assessment on July 18, 2023.

The objectives of the assessment were to document the locations of asbestos building materials, evaluate their condition and develop corrective action plans as required. This assessment is only to be used for the purposes of long-term management and routine maintenance. The results of this assessment are not to be used for construction, renovation, demolition, or project tendering purposes.

### 1.1 Scope of Assessment

The assessment was performed to establish the location and type of asbestos building materials incorporated in the structure(s) and its finishes. The **assessed area** consisted of all parts of the building, excluding the roof.

## 2.0 METHODOLOGY

Pinchin conducted a room-by-room assessment (rooms, corridors, service areas, exterior, etc.) to identify the asbestos-containing building materials as defined in the scope.

The assessment was limited to non-intrusive testing. Concealed spaces such as those above solid ceilings and within shafts and pipe chases were accessed via existing access panels only. Demolition of walls, solid ceilings, structural items, interior finishes or exterior building finishes, to determine the presence of concealed materials was not conducted.

For further details on the methodology including test methods, refer to Appendix III.

## 3.0 BACKGROUND INFORMATION

### 3.1 Building Year of Construction and Additions

Item	Details
Year of Construction	1915
Year(s) of Additions	1960, 1966, 2001

### 3.2 Existing Reports

Pinchin previously prepared the following report, which has been reviewed as part of this assessment:



- Asbestos Reassessment Report, Sacred Heart of Jesus, August 2022, Pinchin File No. 303992.004.

### **3.3 Inaccessible Locations**

Inaccessible locations (rooms or areas), if any, are indicated in the Location List Report in Appendix IV. These locations within the assessed area were not accessible to the surveyor and are therefore not included in the report.

## **4.0 FINDINGS**

The following section summarizes the findings of the assessment and provides a general description of the asbestos-containing materials (ACM) identified and their locations. For details on approximate quantities, condition, friability, accessibility and locations of asbestos materials; refer to the Asbestos Material Summary Report and All Data Report in Appendix V and VI.

### **4.1 Excluded Asbestos Materials**

A number of materials which might contain asbestos were not sampled during this assessment due to limitations in scope and methodology. Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis. These materials are not shown on the drawings in Appendix I. Excluded materials presumed to contain asbestos include:

- Roofing felts and tar, mastics
- Floor levelling compound
- Ceramic tile setting compound
- Elevator and lift brakes
- Electrical components
- Mechanical packing, ropes and gaskets
- Vermiculite
- Adhesives and duct mastics
- Caulking and putties
- Fibre-reinforced paints and coatings
- Paper products
- Soffit and fascia boards
- Fire resistant doors
- Vibration dampers on HVAC equipment



- Terrazzo
- Ropes and gaskets in cast-iron bell and spigot joints
- Sealants on pipe threads




#### 4.2 Summary of Building Materials

This section includes a summary of building materials that have been confirmed asbestos-containing by sample analysis, presumed asbestos-containing by visual identification, or confirmed non-asbestos by sampling or based on the manufacture date and known end of use of asbestos in these products.


The locations of samples from historical assessments performed by Pinchin, have been included on the drawings.

Appendix II presents the asbestos bulk sample analytical results.

Material and Application	Asbestos Type	Photo
Fireproofing is present on structural steel including beams, trusses, joists, corrugated steel deck, concrete deck, columns.	None	
Pipes are either uninsulated or insulated with non-asbestos fibreglass or elastomeric insulation (Armaflex).	None	
Ducts are either uninsulated or insulated with non-asbestos fibreglass (foil-faced or canvas).	None	
Mechanical equipment is either uninsulated or insulated with non-asbestos fibreglass.	None	
All ceiling tiles are non-asbestos from previous sampling, presumed to be non-asbestos based on the date of manufacture determined from the date stamp applied to the top of the tiles and the age of the materials determined from the age of the building.	None	
Plaster is present on walls and ceilings.	None	
Drywall joint compound is present on wall and ceiling finishes.	None	

Material and Application	Asbestos Type	Photo
<p>Asbestos in drywall joint compound was banned in Canada in 1980. The 2001 addition was constructed after 1986 (1980 plus a reasonable non-compliance period based on our experience) and the drywall joint compound is assumed to contain no asbestos.</p>	<p>None</p>	
<p>Vinyl floor tiles, 12"x12", white with blue/red, are present.</p>	<p>Presumed (tile) Presumed (mastic)</p>	
<p>Vinyl floor tiles, 12"x12", grey oatmeal, are present.</p>	<p>Presumed (tile) Presumed (mastic)</p>	
<p>Vinyl floor tiles, 12"x12", white with black specks, are present.</p>	<p>Presumed (tile) Presumed (mastic)</p>	



Material and Application	Asbestos Type	Photo
Vinyl floor tiles and mastic are presumed to be non-asbestos based on historical knowledge of the date of installation (2002).	None	
Gold sink undercoating is present.	Presumed	

## 5.0 RECOMMENDATIONS

### 5.1 General

Perform a detailed intrusive assessment prior to maintenance work, building renovation or demolition operations. The assessment should include destructive testing (e.g., coring and/or removal of building finishes and components), and other hazardous materials (lead, mercury, PCBs, mould, etc.) and materials not tested in this study (e.g., roofing materials, caulking, mastics).

### 5.2 Remedial Work

No remedial work is recommended.

### 5.3 On-going Management and Maintenance

The following recommendations are made regarding on-going management and maintenance work involving the asbestos materials identified.

Maintain the Asbestos Management Program (AMP).

Perform a reassessment of asbestos materials on an annual basis.

Remove asbestos-containing materials (ACM) prior to alteration or maintenance work if ACM may be disturbed by the work. Follow appropriate asbestos precautions for the classification of work being performed.



Sample presumed ACM prior to alteration or maintenance work if the presumed ACM may be disturbed by the work.

Update the asbestos inventory report upon completion of any abatement and removal of asbestos-containing materials.

## **6.0 TERMS AND LIMITATIONS**

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

## **7.0 REFERENCES**

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.
3. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.

\\PIN-HAM-FS02\job\320000s\0320582.000 HWCDDB,Various2023Projects,ASB,CONS\0320582.004 HWCDDB,AllSites,2023,ASB,ASSMT\Deliverables\Sacred Heart of Jesus\Deliverables\320582.004 Asbestos Asmnt Report Sacred Heart of Jesus HWCDDB Aug 31 2023.docx


Template: Master Report for Asbestos Assessment, HAZ, July 29, 2021

**APPENDIX I**  
**Drawings**

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 [www.pinchin.com](http://www.pinchin.com)

**LEGEND:**

- (X) LOCATION NUMBER
  - (⊙) ASBESTOS BULK SAMPLE
  - NAR NO ACCESS TO ROOM/AREA
- ASBESTOS-CONTAINING MATERIALS:**
- VINYL FLOOR TILES AND MASTIC
  - S SINK UNDERCOATING

**CLIENT:**



**LOCATION:**

SACRED HEART OF JESUS  
5 HAMILTON AVENUE  
HAMILTON, ONTARIO

**TITLE:**

ASBESTOS ASSESSMENT  
FLOOR LEVEL 1

**DATE:**

AUGUST 2023

**PROJECT # :**

320582.004

**DRAWN BY:**

EB

**DRAWING:**

1 OF 2

**CHECKED BY:**

EB


**SCALE:**

NTS

NOT ALL KNOWN OR SUSPECTED ASBESTOS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS REASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



905-577-6206 [www.pinchin.com](http://www.pinchin.com)

**LEGEND:**

- (X) LOCATION NUMBER
- ⊙ ASBESTOS BULK SAMPLE
- NAR NO ACCESS TO ROOM/AREA

**ASBESTOS-CONTAINING MATERIALS:**

- VINYL FLOOR TILES AND MASTIC
- S SINK UNDERCOATING

**CLIENT:**



**LOCATION:**

SACRED HEART OF JESUS  
5 HAMILTON AVENUE  
HAMILTON, ONTARIO

**TITLE:**

ASBESTOS ASSESSMENT  
FLOOR LEVEL 2

DATE: AUGUST 2023	PROJECT # : 320582.004
DRAWN BY: EB	DRAWING:  <b>2 OF 2</b>
CHECKED BY: EB	
SCALE: NTS	

**APPENDIX II**  
**Asbestos Analytical Certificates**



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
 EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,  
 App.E



**Customer:** Pinchin Ltd.  
 6-875 Main St West  
 Suite 200  
 Hamilton, Ontario L8S 4P9

**Attn:** Emily Balfour  
 Michael Maiorana

**Lab Order ID:** 71920490  
**Analysis ID:** 71920490\_PLM  
**Date Received:** 8/5/2019  
**Date Reported:** 8/13/2019  
**Date Amended:** 8/30/2019

**Project:** 230748, 5 Hamilton Ave, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, Sacred Heart of Jesus

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0001A	Drywall joint compound on wall, Kindergarten, Location 1022	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_1					Crushed
S0001B	Drywall joint compound on bulkhead, Library, Location 1024	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_2					Crushed
S0001C	Drywall joint compound on wall, Lower Corridor, Location 1030	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_3					Crushed
S0002A - A	Smooth plaster ceiling, Storage, Location 1042	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_4	finish				Crushed
S0002A - B	Smooth plaster ceiling, Storage, Location 1042	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_23	base				Crushed
S0002B - A	Smooth plaster ceiling, Stairwell B, Location 1023	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_5	finish				Crushed
S0002B - B	Smooth plaster ceiling, Stairwell B, Location 1023	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_24	base				Crushed
S0002C - A	Smooth plaster ceiling, Stairwell A, Location 1020	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_6	finish				Crushed

**Disclaimer:** Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Jalen Moore (25)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
 EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,  
 App.E



**Customer:** Pinchin Ltd.  
 6-875 Main St West  
 Suite 200  
 Hamilton, Ontario L8S 4P9

**Attn:** Emily Balfour  
 Michael Maiorana

**Lab Order ID:** 71920490  
**Analysis ID:** 71920490\_PLM  
**Date Received:** 8/5/2019  
**Date Reported:** 8/13/2019  
**Date Amended:** 8/30/2019

**Project:** 230748, 5 Hamilton Ave, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, Sacred Heart of Jesus

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0002C - B	Smooth plaster ceiling, Stairwell A, Location 1020	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_25	base				Crushed
S0002D - A	Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_7	finish				Crushed
S0002D - B	Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_21	base				Crushed
S0002E - A	Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_8	finish				Crushed
S0002E - B	Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_22	base				Crushed
S0003A	Drywall joint compound on bulkhead, Boiler Room, Location 1044	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_9					Crushed
S0003B	Drywall joint compound on bulkhead, Boiler Room, Location 1044	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_10					Crushed
S0003C	Drywall joint compound on bulkhead, Boiler Room, Location 1044	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_11					Crushed

**Disclaimer:** Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Jalen Moore (25)

Analyst

Approved Signatory





# Bulk Asbestos Analysis

By Polarized Light Microscopy  
 EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,  
 App.E



**Customer:** Pinchin Ltd.  
 6-875 Main St West  
 Suite 200  
 Hamilton, Ontario L8S 4P9

**Attn:** Emily Balfour  
 Michael Maiorana

**Lab Order ID:** 71920490  
**Analysis ID:** 71920490\_PLM  
**Date Received:** 8/5/2019  
**Date Reported:** 8/13/2019  
**Date Amended:** 8/30/2019

**Project:** 230748, 5 Hamilton Ave, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, Sacred Heart of Jesus

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0004A	Cementitious overspray on structure, Boiler Room, Location 1044	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_12					Crushed
S0004B	Cementitious overspray on structure, Boiler Room, Location 1044	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_13					Crushed
S0004C	Cementitious overspray on structure, Boiler Room, Location 1044	None Detected		100% Other	Gray Non Fibrous Heterogeneous
71920490PLM_14					Crushed
S0005A	Drywall joint compound on bulkhead, Classroom, Location 1034	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_15					Crushed
S0005B	Drywall joint compound on bulkhead, Classroom, Location 1033	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_16					Crushed
S0005C	Drywall joint compound on bulkhead, Classroom, Location 1035	None Detected		100% Other	White Non Fibrous Heterogeneous
71920490PLM_17					Crushed
S0006A	Sprayed fireproofing on structure, Lower Corridor, Location 1030	None Detected	95% Mineral Wool	5% Other	Gray Fibrous Heterogeneous
71920490PLM_18					Ashed
S0006B	Sprayed fireproofing on structure, Lower Corridor, Location 1030	None Detected	95% Mineral Wool	5% Other	Gray Fibrous Heterogeneous
71920490PLM_19					Ashed

**Disclaimer:** Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Jalen Moore (25)

Analyst

Approved Signatory



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and 40 CFR, Part 763, Subpart E,  
App.E



**Customer:** Pinchin Ltd.  
6-875 Main St West  
Suite 200  
Hamilton, Ontario L8S 4P9

**Attn:** Emily Balfour  
Michael Maiorana

**Lab Order ID:** 71920490  
**Analysis ID:** 71920490\_PLM  
**Date Received:** 8/5/2019  
**Date Reported:** 8/13/2019  
**Date Amended:** 8/30/2019

**Project:** 230748, 5 Hamilton Ave, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, Sacred Heart of Jesus

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
S0006C	Sprayed fireproofing on structure, Lower Corridor, Location 1030	None Detected	95% Mineral Wool	5% Other	Gray Fibrous Heterogeneous
71920490PLM_20					Ashed

**Disclaimer:** Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Jalen Moore (25)

Analyst

Approved Signatory

719 220 490

Version 1-15-2012

719 220 490 revised

Invoice to:

ap@pinchin.com



Scientific Analytical Institute

4604 Dundas Dr.

Greensboro, NC 27407

Phone: 336.292.3888

Fax: 336.292.3313

Email: lab@sailab.com

<b>Client:</b> Pinchin Ltd. <b>Contact:</b> Emily Balfour 6-875 Main Street West, Suite 200, Hamilton ON L8S 4P9 <b>Address:</b> <b>Phone:</b> 905-577-6206 <b>Fax:</b> 905-577-6207 <b>Email:</b> ebalfour@pinchin.com mmalorana@pinchin.com 230748, 5 Hamilton Ave, Hamilton, Ontario, Hamilton-Wentworth Catholic School Board, Sacred Heart of Jesus	<b>Client Notes:</b> **Only analyze second grey layer for S0002A-C (highlighted samples). Amend results to Analysis ID T1920490_PLM**	<b>P.O. #:</b> 230748 <b>Date Submitted:</b> 7/31/2019 <b>Analysis:</b> PLM (NO Stop Positive) <b>TurnAroundTime:</b> 3 Days	<b>Instructions:</b> Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>" Begin Samples with a "<<" above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data.	Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com
--	---	---	--	---

Sample Number	Data 1 (Lab use only)	Sample Description	Data 2 (Lab use only)
---------------	-----------------------	--------------------	-----------------------

S0001A		Drywall joint compound on wall, Kindergarten, Location 1022	
S0001B		Drywall joint compound on bulkhead, Library, Location 1024	
S0001C		Drywall joint compound on wall, Lower Corridor, Location 1030	
S0002A		Smooth plaster ceiling, Storage, Location 1042	
S0002B		Smooth plaster ceiling, Stairwell B, Location 1023	
S0002C		Smooth plaster ceiling, Stairwell A, Location 1020	
S0002D		Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	
S0002E		Smooth plaster wall (behind drywall), Lower Corridor, Location 1030	
S0003A		Drywall joint compound on bulkhead, Boiler Room, Location 1044	


Accepted

Rejected

M. Vogel 7/30/10

S0003B  
S0003C  
S0004A  
S0004B  
S0004C  
S0005A  
S0005B  
S0005C  
S0006A  
S0006B  
S0006C  
>>

Drywall joint compound on bulkhead, Boiler Room, Location 1044  
Drywall joint compound on bulkhead, Boiler Room, Location 1044  
Cementitious overspray on structure, Boiler Room, Location 1044  
Cementitious overspray on structure, Boiler Room, Location 1044  
Cementitious overspray on structure, Boiler Room, Location 1044  
Drywall joint compound on bulkhead, Classroom, Location 1034  
Drywall joint compound on bulkhead, Classroom, Location 1033  
Drywall joint compound on bulkhead, Classroom, Location 1035  
Sprayed fireproofing on structure, Lower Corridor, Location 1030  
Sprayed fireproofing on structure, Lower Corridor, Location 1030  
Sprayed fireproofing on structure, Lower Corridor, Location 1030



**APPENDIX III**  
**Methodology**



## 1.0 GENERAL

An inspection was conducted to identify the asbestos-containing materials (ACM) incorporated in the structure and its finishes as defined by the scope of work.

Information regarding the location and condition of ACM encountered and visually estimated quantities were recorded. The locations of any samples collected were recorded on small-scale plans. As-built drawings and previous reports were referenced where provided.

Sample collection (where performed) was conducted in accordance with our Standard Operating Procedures.

The inspection for asbestos included friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure.

Where samples were collected, a separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Where samples were collected, samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

Where samples were collected, the asbestos analysis was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

Where samples were collected, the analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

Where samples were collected, analytical results were compared to the following criteria.



<b>Jurisdiction*</b>	<b>Friable</b>	<b>Non-Friable</b>
Ontario	0.5%	0.5%

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials were evaluated in order to make recommendations regarding remedial work. The priority for remedial action was based on several factors:

- Friability (friable or non-friable);
- Condition (good, fair, poor, debris);
- Accessibility (ranking from accessible to all building users to inaccessible);
- Visibility (whether the material is obscured by other building components).
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition).

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

## **METHODOLOGY ANNEX A EVALUATION CRITERIA**



## EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

### EVALUATION OF CONDITION

#### Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

<b>Good</b>	Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred.
<b>Poor</b>	A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed.

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

#### Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

<b>Good</b>	Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated.
<b>Fair</b>	Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired.

---

<b>Poor</b>	Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely.
-------------	---

---

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

### Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

---

<b>Good</b>	No significant damage or deterioration. Still serving its intended use as a building material or finish.
<b>Fair</b>	Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes.
<b>Poor</b>	Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement.

---

### Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

---

<b>Good</b>	No significant damage or deterioration. Still serving its intended use as a building material or finish.
-------------	--

---

---

<b>Fair</b>	Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes.
<b>Poor</b>	Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable.

---

### Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

---

<b>Debris</b>	Debris may be friable or non-friable but is always identified as debris.
---------------	--

---

### Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

## EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

<b>Access (A)</b>	Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops, warehouses)
<b>Access (B)</b>	Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases.
<b>Access (C) and Visible</b>	Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. Visible column on HMIS sheets will say YES.
<b>Access (C) and not Visible</b>	Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. Visible column on HMIS sheets will say NO.
<b>Access (D)</b>	Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D.

## ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

### Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

**Table I Decision Matrix for Friable ACM**

Access	Condition			Debris
	Good	Fair	Poor	
(A)	Action 5 <sup>1</sup>	Action 5 <sup>2</sup>	Action 3	Action 1
(B)	Action 7	Action 6 <sup>3</sup>	Action 3	Action 1
(C) Visible	Action 7	Action 6	Action 3	Action 2
(C) Not Visible	Action 7	Action 7	Action 4	Action 2
(D)	Action 7	Action 7	Action 7	Action 7

**Table II Decision Matrix for Potentially Friable and Non-Friable ACM**

Access	Condition			Debris
	Good	Fair	Poor	
(A)	Action 7	Action 7 <sup>4</sup>	Action 3	Action 1
(B)	Action 7	Action 7	Action 3	Action 1
(C) Visible	Action 7	Action 7	Action 4	Action 2
(C) Not Visible	Action 7	Action 7	Action 4	Action 2
(D)	Action 7	Action 7	Action 7	Action 7

### Action Definitions

The following are the definitions in the Action Matrix Table presented above:

#### Action Definitions

<b>Action 1</b>	Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions.
-----------------	--

<sup>1</sup> If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

<sup>2</sup> If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

<sup>3</sup> If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

<sup>4</sup> Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons



---

**Action Definitions**

---

<b>Action 2</b>	<p>Precautions for Access Which may Disturb ACM Debris</p> <p>Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up.</p>
<b>Action 3</b>	<p>ACM Removal</p> <p>Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed.</p>
<b>Action 4</b>	<p>Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM.</p>
<b>Action 5</b>	<p>Proactive ACM Removal</p> <p>Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM.</p>
<b>Action 6</b>	<p>ACM Repair</p> <p>Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room</p>
<b>Action 7</b>	<p>Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year).</p>

---

**APPENDIX IV**  
**Location List**

**Client:** Hamilton-Wentworth Catholic District Sch  
**Building Name:** Sacred Heart of Jesus  
**Survey Date:**  
**Building Phases:** A: 1915

**Site:** 5 Hamilton Ave, Hamilton, ON  
**Last Re-Assessment:** 2023-07-18

Location No.	Name or Description	Area ft <sup>2</sup>	Floor No.	Bldg. Phase	Notes
1000	Presumed Asbestos-Containing Materials	0		A	Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis.
1001	Office	0	1	A	
1002	Principals Office	0	1	A	
1003	Electrical Room	0	1	A	
1004	Storage	0	1	A	
1005	Work room	0	1	A	
1006	Conference Room	0	1	A	
1007	Staff Washroom-Women's	0	1	A	
1008	Staff Washroom-Mens	0	1	A	
1009	Handicap Washroom	0	1	A	
1010	Classroom 101	0	1	A	
1011	Classroom-102	0	1	A	
1012	Classroom-103	0	1	A	
1013	Classroom-104	0	1	A	
1014	Classroom-105	0	1	A	
1015	Classroom-106	0	1	A	
1016	Staff Room	0	1	A	
1017	Machine Room	0	1	A	
1018	Elevator	0	1	A	
1019	Custodian Room	0	1	A	
1020	stairwell A	0	1	A	
1021	Boys Washroom	0	1	A	
1022	Kindergarten	0	1	A	
1023	stairwell B	0	1	A	
1024	Library	0	1	A	
1025	computer room	0	1	A	
1026	Library Office	0	1	A	
1027	Girls Washroom	0	1	A	
1028	Gym Storage	0	1	A	
1029	Gymnasium	0	1	A	
1030	Lower Corridor	0	1	A	
1031	Storage	0	1	A	
1032	Classroom-201	0	2	A	
1033	Classroom-202	0	2	A	
1034	Classroom-203	0	2	A	
1035	Special Education	0	2	A	
1036	Special Education Office	0	2	A	
1037	Staff Washroom	0	2	A	
1038	Upper Corridor	0	2	A	
1039	Custodian Closet	0	2	A	
1040	Storage	0	2	A	
1041	Storage	0	2	A	
1042	Storage	0	2	A	
1043	communication room	0	2	A	
1044	Boiler Room	0	2	A	



**APPENDIX V**  
**Summary Report / Sample Log**

**Client:** Hamilton-Wentworth Catholic District Sch

**Site:** 5 Hamilton Ave, Hamilton, ON

**Building Name:** Sacred Heart of Jesus

**Survey Date:**

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	S0001 ABC	Ceiling, Wall, Ceiling   Bulkhead   Drywall And Joint Compound	1022,1024,1030	A	0	0	0	100	None Detected	No	
Asbestos	S0002 ABCDE	Ceiling, Wall     Plaster	1020,1023,1030,1042	A	0	0	0	100	None Detected	No	
Asbestos	S0003 ABC	Ceiling   Bulkhead   Drywall And Joint Compound	1043,1044	A	0	0	0	100	None Detected	No	
Asbestos	S0004 ABC	Structure     Overspray	1043,1044	A	0	0	0	100	None Detected	No	
Asbestos	S0005 ABC	Ceiling   Bulkhead   Drywall And Joint Compound	1032,1033,1034,1035,1038	A	0	0	0	100	None Detected	No	
Asbestos	S0006 ABC	Structure     Fireproofing (fibrous)	1030	A	0	0	0	0	None Detected	No	
Asbestos	V9500	Floor     Vinyl Floor Tile And Mastic   12x12 Grey Oatmeal, 12x12 White W Blue/red, 12x12 White With Black Specks	1028,1029,1042,1043	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other   Sink   Mastic, Gold   Undercoating	1026	A	0	0	1	0	Presumed Asbestos	Yes	NF
Asbestos	V9500	Other     N/a   Roofing Felts And Tar, Mastics, Floor Levelling Compound, Ceramic Tile Setting Compound, Electrical Components, Mechanical Packing, Ropes And Gaskets, Vermiculite, Adhesives And Duct Mastics, Caulking And Putties, Fibre-reinforced Paints And Coatings, Paper Products, Soffit And Fascia Boards, Fire Resistant Doors, Stucco, Plaster Or Other Cementitious Parge Coatings, Vibration Dampers On Hvac Equipment, Terrazzo, Ropes And Gaskets In Cast-iron Bell And Spigot Joints, Sealants On Pipe Threads	1000	A	0	0	0	100	Presumed Asbestos	Yes	NF
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Long Fissure Random Pinhole	1028	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole (date Stamped 2002)	1002	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Gypsum	1021,1027	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole	1010,1023	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole ( Date Stamped 2002)	1012	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole (date Stamped 2002)	1001,1003,1004,1005,1007,1009,1013,1014,1015 1016,1019,1022,1024,1025,1026,1030,1031	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short	1032,1035,1036,1037	A	0	0	0	100	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0000	Fissure Random Pinhole Date Stamped 2002 Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole- Date Stamped 2002	1038	A	0	0	0	100	Asbestos Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   2x4 Short Fissure Random Pinhole-date Stamped 2002	1033,1034,1040,1041	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   Short Fissure Random Pinhole	1020	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Ceiling Tiles (lay-in)   Short Fissure Random Pinhole (date Stamped 2002)	1006,1008,1011	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Ceiling     Metal	1018	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Duct     Fibreglass	1011	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Ceramic Tiles	1009	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Concrete (poured)	1017	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Terrazzo	1020,1021,1023,1027,1030,1031,1038	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)	1008	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Blue W White Fleck-installed 2002	1033,1034,1035,1036	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Blue W White/blue Fleck (installed 2002)	1011,1012,1013,1016	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Blue W White/blue Fleck (installed In 2002)	1010	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Brown W White Fleck	1010,1037	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Brown W White Fleck (installed 2002)	1003,1004,1006,1011,1012,1015,1022	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 Brown W White Fleck-installed 2002	1032,1039,1040,1041	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 White W Blue Fleck (installed 2002)	1001,1002,1005,1013,1014,1015,1016,1019	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 White W Blue Fleck - Installed 2002	1032	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 White W Blue Fleck-installed 2002	1034	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   12x12 White W Blue Fleck (installed 2002)	1016	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   Blue W White Blue Fleck (installed 2002)	1022	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Floor     Vinyl Floor Tile (no Mastic)   White W	1033	A	0	0	0	100	Non	No	

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
		Blue Fleck							Asbestos		
Asbestos	V0000	Other   Deck   Steel   Open Web Steel Joist Support	1011,1014	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Piping     Fibreglass	1011,1029,1043,1044	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Piping   All   Not Insulated	1028	A	0	0	0	0	Non Asbestos	No	
Asbestos	V0000	Wall     Drywall And Joint Compound   Installed 2002	1001,1002,1006	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall     Masonry   Concrete Block	1007,1010,1011,1013	A	0	0	0	100	Non Asbestos	No	
Asbestos	V0000	Wall     Metal	1018	A	0	0	0	0	Non Asbestos	No	

## Legend:

Sample number		Units		
S####	Asbestos sample collected	SF	Square feet	NF Non Friable material.
L####	Paint sample collected	LF	Linear feet	F Friable material
P####	PCB sample collected	EA	Each	PF Potentially Friable material
M####	Mould sample collected	%	Percentage	
V####	Material visually similar to numbered sample collected			
V0000	Known non Hazardous Material			
V9000	Material is visually identified as Hazardous Material			
V9500	Material is presumed to be Hazardous Material			
[Loc. No.]	Abated Material			

**APPENDIX VI**  
**HMIS All Data Report**

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1000 : Presumed Asbestos-Containing Materials  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:**

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Other		N/A, Roofing felts and tar, mastics, Floor levelling compound, Ceramic tile setting compound, Electrical components, Mechanical packing, ropes and gaskets, Vermiculite, Adhesives and duct mastics, Caulking and putties, Fibre-reinforced paints and coatings, Paper products, Soffit and fascia boards, Fire resistant doors, Stucco, plaster or other cementitious parge coatings, Vibration dampers on HVAC equipment, Terrazzo, Ropes and gaskets in cast-iron bell and spigot joints, Sealants on pipe threads			D	N		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF

Where present, these materials are assumed to contain asbestos until otherwise proven by sampling and analysis.

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1001 : Office  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y										
Structure		Steel, open web steel joist support			A	Y										
Wall		Drywall and joint compound, installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1002 : Principals Office  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Other		Steel, open web steel joist support			A	Y										
Piping		Fibreglass			A	Y										
Wall		Drywall and joint compound, installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1003 : Electrical Room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			A	Y										
Piping		Fibreglass			A	Y										
Structure	Deck	Steel			A	Y										
Wall		Masonry, concrete block			A	Y										



**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1004 : Storage  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			A	Y										
Structure		Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1005 : Work room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1006 : Conference Room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			A	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Drywall and joint compound, installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1007 : Staff Washroom-Women's**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 1**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Ceramic Tiles			A	Y										
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			A	Y										
Structure	Deck	Steel			C	Y										
Wall		Masonry, concrete block			A	Y		100			%	V0000	Non-Asbestos		None	

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1008 : Staff Washroom-Mens**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 1**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1009 : Handicap Washroom  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Ceramic Tiles			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1010 : Classroom 101  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white/blue fleck (installed in 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y		100			%	V0000	Non-Asbestos		None	

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1011 : Classroom-102  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white/blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Other	Deck	Steel, open web steel joist support			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry, concrete block			A	Y		100			%	V0000	Non-Asbestos		None	

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1012 : Classroom-103  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole ( date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white/blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1013 : Classroom-104  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white/blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y		100			%	V0000	Non-Asbestos		None	

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1014 : Classroom-105  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Other	Deck	Steel, open web steel joist support			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Wall		Masonry, concrete block			A	Y										



**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1015 : Classroom-106  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Fibreglass			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1016 : Staff Room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white/blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

ALL DATA REPORT

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1017 : Machine Room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Concrete (poured)			A	Y		100			%	V0000	Non-Asbestos		None	
Structure	Deck	Steel, OPEN WEB STEEL JOIST SUPPORT			C	Y										
Wall		Masonry, CONCRETE BLOCK			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1018 : Elevator  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Metal			A	Y						V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic	ALL		A	Y		25			SF	V9500	[None]		[Abated]	
Wall		Metal			A	Y						V0000	Non-Asbestos		None	

**Client:** Hamilton-Wentworth Catholic District Sch    **Site:** Elementary  
**Location:** #1019 : Custodian Room                      **Floor:** 1  
**Survey Date:** 2023-07-18

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch    **Site:** Elementary  
**Location:** #1020 : stairwell A                              **Floor:** 1  
**Survey Date:** 2023-07-18

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), short fissure random pinhole			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Plaster			C	Y		100			%	S0002C	None Detected	N.D.	None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1021 : Boys Washroom  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 gypsum			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1022 : Kindergarten  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), blue w white blue fleck (installed 2002)			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Drywall and joint compound			A	Y						S0001A	None Detected	N.D.	None	
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1023 : stairwell B  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Plaster			C	Y		100			%	S0002B	None Detected	N.D.	None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1024 : Library  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0001B	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Carpet			A	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1025 : computer room**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 1**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Carpet			A	Y										
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure		Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1026 : Library Office**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 1**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Carpet			A	Y										
Mechanical Equipment		Not Insulated			C	Y										
Other	Sink	Mastic, Gold, undercoating			A	N		1(7)			EA	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1027 : Girls Washroom  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 gypsum			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1028 : Gym Storage  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling <sup>1</sup>		Ceiling Tiles (lay-in), 2X4 long fissure random pinhole			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 12x12 grey oatmeal			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping <sup>2</sup>	All	Not Insulated	ALL		A	Y						V0000	Non-Asbestos		None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

- 1 - 1999 Manufacture date stamp on backside
- 2 - Material observed to be abated during 2018 reassessment



**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1029 : Gymnasium  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		None Found														
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile and Mastic, 12x12 white with black specks			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1030 : Lower Corridor  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 1

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound			C	Y		100			%	V0001	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			A	Y										
Structure		Fireproofing (Fibrous)			C	N						S0006ABC	None Detected	N.D.	None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Drywall and joint compound			A	Y		100			%	S0001C	None Detected	N.D.	None	
Wall		Plaster		Drywall and joint compound	D	N						S0002DE	None Detected	N.D.	None	
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1031 : Storage**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 1**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole (date stamped 2002)			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1032 : Classroom-201**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 2**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole date stamped 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	V0005	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck - installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1033 : Classroom-202  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole-date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0005B	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), white w blue fleck			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1034 : Classroom-203  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole-date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0005A	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 white w blue fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1035 : Special Education  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall and joint compound			C	Y		100			%	S0005C	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1036 : Special Education Office  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 blue w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1037 : Staff Washroom  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Duct		Not Insulated			C	Y										
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck			A	Y		100			%	V0000	Non-Asbestos		None	
Mechanical Equipment		Not Insulated			C	Y										
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1038 : Upper Corridor  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole- date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Ceiling		Drywall and joint compound			C	Y		100			%	V0005	None Detected	N.D.	None	
Duct		Not Insulated			C	Y										
Floor		Ceramic Tiles			A	Y										
Floor		Terrazzo			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1039 : Custodian Closet  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1040 : Storage**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 2**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole-date stamped 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client: Hamilton-Wentworth Catholic District Sch**  
**Location: #1041 : Storage**  
**Survey Date: 2023-07-18**

**Site: Elementary**  
**Floor: 2**

**Building Name: Sacred Heart of Jesus**  
**Room #:**  
**Last Re-Assessment: 2023-07-18**

**Area (sqft): 0**

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Ceiling Tiles (lay-in), 2x4 short fissure random pinhole-date stamped 2002			C	Y		100			%	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile (No Mastic), 12x12 brown w white fleck-installed 2002			A	Y		100			%	V0000	Non-Asbestos		None	
Piping		Fibreglass			C	Y										
Structure	Deck	Concrete (precast), concrete			C	Y										
Wall		Masonry, concrete block			A	Y										



**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1042 : Storage  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling		Plaster			C	Y		100			%	S0002A	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic, 12x12 white w blue/red			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1043 : communication room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Bulkhead	Drywall and joint compound			C	Y						V0003	None Detected	N.D.	None	
Floor		Vinyl Floor Tile and Mastic, 12x12 white w blue/red			A	Y		100(7)			%	V9500	Presumed Asbestos		Presumed Asbestos	NF
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Structure		Overspray			C	Y		100			%	V0004	None Detected	N.D.	None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

**Client:** Hamilton-Wentworth Catholic District Sch  
**Location:** #1044 : Boiler Room  
**Survey Date:** 2023-07-18

**Site:** Elementary  
**Floor:** 2

**Building Name:** Sacred Heart of Jesus  
**Room #:**  
**Last Re-Assessment:** 2023-07-18

**Area (sqft):** 0

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling	Bulkhead	Drywall and joint compound			C	Y		33			%	S0003ABC	None Detected	N.D.	None	
Floor		Concrete (poured), concrete			A	Y										
Piping		Fibreglass			A	Y		100			%	V0000	Non-Asbestos		None	
Structure		Overspray			C	Y						S0004ABC	None Detected	N.D.	None	
Structure	Deck	Steel, open web steel joist support			C	Y										
Wall		Masonry, concrete block			A	Y										

## Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
V####	Material visually similar to numbered sample collected	LF	Linear feet	V	Visible
V0000	Known non-asbestos material	EA	Each	AP	Air Plenum
V9000	Visually identified as an asbestos material	%	Percentage	F	Friable material
V9500	Material is presumed to be an asbestos material			NF	Non Friable material
				PF	Potentially Friable material

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material

Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is known to contain regulated concentrations of asbestos; either by analytical results or visible identification (use of the V9000 code).
	The material is presumed to contain asbestos; based on visual appearances; typically a material known to historically contain asbestos; however, not sampled due to limited access or the destructive nature of the sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				